

Step	Location	Procedure	By	Date			
1	DC	Issue Traveler	+	05.08.11			
2	ST	Remove from finished inventory  Oty Part Number Description  K 1 00 0 5  R 23 0 76  B 21 1 8 4					
			PL	05/08/15			
3	PK	Open box. Remove D500-572-021 paperwork and replace with new D500-572-021 paperwork.	PL	05/08/15			
4	PK	Ensure paperwork and P/N's match with boxes.	PL	05/08/15			
5	QC5	Inspect work to Step 5	4	50815			
6	ST	Return to finished inventory	DL	05/08/15			
7	AC	Cost / part:	Suz	05.08-26			
8	DC	Close W/O Inspect Level 21	D	05/8/26			
(Note: Attach a copy of Custom W/O to each of the W/O's listed in Step 2 above)							

	Rev	Date	Change	Revised By	Approved
١	Α	05.08.10	New Issue	KJ/JLM	



**Dart Aerospace Ltd** 

Page 1

L/T Lot Number Listing - (LTMAST01)

From Item Number: From Customer Code:

Having a status of:

[K10005] To [K10005] [] To [ZZZZZZZZZZZ]

[] oT []

į

[Available] To [Available]

Sort by:

[Item Number]

Report type:

[Detail]

Activity:

[No Activity History]

Item/Lot Number	Location/ Customer#	Uniq. Last Document	Reference/ Vendor#	Stock Dt./ Expiry Quar. Dt. On Wa	Ot./ Status/ ? War. Dt.	On Con? Con. Dt.	Qty. Rec	Qty. Avail	Cost	Price
K10005 21184	MAIN	Bearpaw kit 13" x 10 0 DJ0000001	6"	Category Code: DA 30/06/2005 No	MACH Available	UOM: Ea	ch 3.00 0 0	3.00	481.50 0 0	0.00
23076	MAIN	0 DJ000001		30/06/2005 No	Available	No	5.00 0 0	5.00	802.50 0 0	0.00

## 2 lots printed

512. Erns